



## Update - February 2006

Just a quick update to let you all know that things went to plan, well mostly to plan. The new engine is in and running perfectly. We had a slight, well huge hiccup though, just after the engine had been started for the first time we were doing some "still testing" which ended in a loud "Bang". The crown wheel carrier housing ended up in a million bits, - something that we really didn't need to happen. New bits for the diff had to be bought in from the USA. At least now I can say that the diff has been fixed and we will be heading to Timaru on Wednesday night as planned. We can't wait to get the Truck out on the Race Track.



From the right



From the back



From the left

Some other little bits we've done, is adding a muffler to the Truck (it's very loud). Plus new Chrome wheels rims to set the truck off. The Freightliner is going back out on the track in sure style.

Look out for our Newsletter next week with all the news from Timaru.

